

PERRY JOHNSON LABORATORY ACCREDITATION, INC.

Certificate of Accreditation

Perry Johnson Laboratory Accreditation, Inc. has assessed the Laboratory of:

A & B Environmental Services 10100 East Freeway, Suite 100, Houston, TX 77029

(Hereinafter called the Organization) and hereby declares that Organization is accredited in accordance with the recognized International Standard:

ISO/IEC 17025: 2005 EPA NLLAP-LQSR Revision 3.0

This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (as outlined by the joint ISO-ILAC-IAF Communiqué dated January 2009):

Environmental Testing (As detailed in the supplement)

Accreditation claims for such testing and/or calibration services shall only be made from addresses referenced within this certificate. This Accreditation is granted subject to the system rules governing the Accreditation referred to above, and the Organization hereby covenants with the Accreditation body's duty to observe and comply with the said rules.

For PJLA:

Fo

Initial Accreditation Date: Issue Date:

ate:

Expiration Date:

February 10, 2012

October 6, 2016

October 6, 2018

Revision Date:

Accreditation No:

Certificate No:

November 15, 2017

71390

L16-299-R1

Tracy Szerszen President/Operations Manager

Perry Johnson Laboratory Accreditation, Inc. (PJLA) 755 W. Big Beaver, Suite 1325 Troy, Michigan 48084 The validity of this certificate is maintained through ongoing assessments based on a continuous accreditation cycle. The validity of this certificate should be confirmed through the PJLA website: www.pjlabs.com





Certificate of Accreditation: Supplement

ISO/IEC 17025:2005 EPA NLLAP-LQSR Revision 3.0

A & B Environmental Services

10100 East Freeway, Suite 100, Houston, TX77029 Contact: Mark Johnston Phone: 713-453-6060

Accreditation is granted to the facility to perform the following testing:

FIELD OF TEST	ITEMS, MATERIALS OR PRODUCTS TESTED	SPECIFIC TESTS OR PROPERTIES MEASURED	SPECIFICATION, STANDARD METHOD OR TECHNIQUE USED
Environmental ^F	Paint Chips, Dust and	Lead (Pb)	EPA 3050B
	Soil		EPA 6010C

1. The presence of a superscript F means that the laboratory performs testing of the indicated parameter at its fixed location. Example: Outside Micrometer^F would mean that the laboratory performs this testing at its fixed location.

